

# Rice White Building

Asheville, NC

The Rice White Building, located at 19 Biltmore Ave. was being renovated for office/retail development. The south side of the structure was in poor condition due to weathering of the brick and mortar joints.

An approximately 2" thick layer of lightly reinforced, [wet mix shotcrete](#) was placed over the exposed south wall to protect the brick from further weathering damage.

GC: Heartwood Renovations & Building, Inc.  
Engineer: Kloesel Engineering  
Geotechnical Contractor: WEC

